CLASSIFIED MISSSAGE	DOUGHO
184 ØZ 31 OCT 62 SECRET	C/DD 4 DDR 5 DD 3 6 P 7
DIRECTOR 25X1	ZEIAD MB
OSA (1-2-3-4-5-6-7-8-9-1Ø)	ROUTINE
° ' S/C (11) TOR: 1954z 31 OCT 62	IN 54Ø58
11 INFO	сітв 2
ARE AS FOLLOWS:	OF FIELD OPERATIONS
1. 201 ON STANDBY AS BACKUP FOR 205 AND 2. 202 AND 203 BEING REVIEWED AT	204. OVERHAUL FOR
PARTIAL DISASSEMBLY AND INCORPORATION OF REC	ENT SIGNIFICANT

3. 204 IS BEING MOUNTED ON THE TEST STAND.

ENGINEERING CHANGES, INCLUDING REAR MOUNT LOWER LUGS.

4. NO. 205/121 MADE FLIGHTS 41, 42, AND 43. OPERATION WAS GENERALLY SATISFACTORY WITH ATTAINMENT OF SPEED OF 1.95 MN AT 54,000 FEET DURING FLIGHT 42. ENGINE RELIGHT TESTS ON FLIGHT NBR 43 WAS SUCCESSFUL AT .8 MN AT 26,000 FEET BUT OTHER RELIGHT ATTEMPTS AT HIGHER MN AND HIGHER ALTITUDES WERE NOT SATISFACTORY AND THIS IS BEING INVESTIGATED FURTHER. INITIAL

SECRET

GROUP 1 Excluded from outemeti downgrading and declassification

REPRODUCTION BY POPHERICASE 2004/06/40/COLOUR DP89B00980IRD00300070079-9

Approved For Release 2004/05/13 : CIA-RDP89B00980R000300070079-9

25X1

SECRET

(IN 54058)

PAGE TWO

INDICATIONS FROM CHASE PLANE OBSERVATIONS IS THAT CIS DIDN'T FIRE ON UNSUCESSFUL RELIGHT ATTEMPTS. VISUAL INSPECTION OF BOTH ENGINES SATISFACTORY AND THEY ARE READY FOR NEXT GO.

END OF MESSAGE